


# REPORT

## TRUESDAIL LABORATORIES, INC.

CHEMISTS - MICROBIOLOGISTS - ENGINEERS  
RESEARCH - DEVELOPMENT - TESTING



14201 FRANKLIN AVENUE  
TUSTIN, CALIF. 92680  
AREA CODE 714 • 730-6239  
AREA CODE 213 • 225-1564  
FAX 714 • 730-6462

CLIENT: Douglas Aircraft Company  
Internal Mail Code C6-59  
19503 South Normandie Ave.  
Torrance, CA 90502  
ATTN: Dan Palacios

REPORT DATE: April 8, 1992

RECEIVED: March 25, 1992

LABORATORY NUMBER: 49732-3 ✓

Water from Stormdrain, Torrance Facility  
P.O. No: T & M 25998C

First Quarter, 1992, Analysis as Required by NPDES Permit #CA0001414

### RESULTS

Total Flow, GPD	4,565
Temperature, °F	64
pH, Units (EPA 150.1)	7.8

Parameter	Method	MILLIGRAMS PER LITER	
		Detection Limit	Concentration
Biochemical Oxygen Demand	405.1	2.0	9.6
Chromium	200.7	0.01	ND
Oil and Grease	413.1	6.0	ND
Settleable Solids (ml/L/hr)	160.5	0.20	ND
Total Suspended Solids	160.2	4.0	6.0

\*ND = Not detected, below detection limit



Respectfully Submitted,  
Truesdail Laboratories, Inc.

Thomas Herrin, Manager  
Environmental Field Services

This report applies only to the sample, or samples, investigated and is not necessarily indicative of the quality or condition of apparently identical or similar products. As a mutual protection to clients, the public and these Laboratories, this report is submitted and accepted for the exclusive use of the client to whom it is addressed and upon the condition that it is not to be used, in whole or in part, in any advertising or publicity matter without prior written authorization from these Laboratories.